

# Oil Field Environmental Incident Summary

**Incident:** 20140903154058      **Date/Time of Notice:** 09/03/2014 15:40

**Responsible Party:** BOH Inc.

**Well Operator:** MESA OIL SERVICES LLC

**Well Name:** CARL SPACKLER SWD 1

**Field Name:** SATHER LAKE

**Well File #:** 90307

**Date Incident:** 9/1/2014

**Time Incident:** 21:30

**Facility ID Number:**

**County:** MCKENZIE

**Twp:** 149

**Rng:** 101

**Sec:** 30

**Qtr:**

**Location Description:**

**Submitted By:** Thomas Norman

**Received By:**

**Contact Person:** Joel Young  
13745 55th St NW  
Williston, ND 58801

**General Land Use:** Well/Facility Site

**Affected Medium:** Well/Facility Soil

**Distance Nearest Occupied Building:** 2 Mile

**Distance Nearest Water Well:**

**Type of Incident:** Other

**Release Contained in Dike:** Yes - On Facility Site

**Reported to NRC:** No

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine	15	Barrels	15	Barrels		
Other						

**Description of Other Released Contaminant:**

**Inspected:**

**Written Report Received:**

**Clean Up Concluded:**

**Risk Evaluation:**

No risk. Source of spill was contained very quickly within the well site. No injuries occurred. Brine was promptly cleaned up and disposed of at site.

**Areal Extent:**

**Potential Environmental Impacts:**

No potential environmental impacts. Brine was vacuumed and disposed of at approved site. Affected ground soil was shoveled and disposed of at a solid waste disposal.

**Action Taken or Planned:**

BOH was notified of the spill and informed to clean up the spill immediately after containment occurred. BOH is in process of instructing/re-training all drivers on necessary steps to safely and properly offload.

**Wastes Disposal Location:****Agencies Involved:****Updates**

---

**Date:** 9/3/2014      **Status:** Reviewed - Assigned to Other Agency**Author:** Martin, Russell**Updated Oil Volume:****Updated Salt Water Volume:****Updated Other Volume:****Updated Other Contaminant****Notes:**

Release, due to unspecified cause, remained on location according to the report. NDIC retains oversight.